

## Partial List of Orphan Sites in Indiana

(For further information about these sites contact Mary Estrada at 317-233-0933)

County **Adams**

Permit	<b>47089</b>	1 HUGO & EMMA BOERGER	28	N	14	E	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>47951</b>	2 SMITLEY	25	N	15	E	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>47955</b>	3 SMITLEY-BROOKS	25	N	15	E	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48174</b>	1 SMITLEY/ABNET	25	N	15	E	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48676</b>	2 HUGO BOERGER	28	N	14	E	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Properly fill and level the pits and restore the wellsites to as near pre-excavation contours as possible per 312 IAC 16-5-12.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Properly fill and level the pits and restore the wellsites to as near pre-excavation contours as possible per 312 IAC 16-5-12.

Permit	<b>48704</b>	3 HUGO BOERGER	28	N	14	E	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Properly fill and level the pits and restore the wellsites to as near pre-excavation contours as possible per 312 IAC 16-5-12.

Permit	<b>35128</b>	1 FRANK BRADEN	10	N	8	E	Section 11
--------	--------------	----------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>35213</b>	1 RAY & ALTA CALENDAR	10	N	8	E	Section 24
--------	--------------	-----------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>26894</b>	2-A Alfred Weyer	3	S	4	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>27235</b>	5 WM. WEYER	3	S	4	W	Section 26
The well noted above requires the following corrective action(s) to bring it into compliance:							
Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>27255</b>	W-13 LAWRENCE OSER	3	S	4	W	Section 26
The well noted above requires the following corrective action(s) to bring it into compliance:							
Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.							
Permit	<b>27362</b>	W-17 RENUS LEINENBACH	3	S	4	W	Section 26
The well noted above requires the following corrective action(s) to bring it into compliance:							
Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.							
Permit	<b>27367</b>	W-15 RENUS LEINENBACH	3	S	4	W	Section 26
The well noted above requires the following corrective action(s) to bring it into compliance:							
Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.							
Repair the pipes conveying waste fluids and repair all damage caused by the escape of fluids per 312 IAC 16-5-13.							
Permit	<b>28288</b>	K-1 Aloysius Kippenbrock	3	S	4	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>32007</b>	8 ALFRED WEYER & SON INC.	3	S	4	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>39411</b>	KB 1 ALOYSIUS KIPPENBROCK	3	S	4	W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>39412</b>	KB-10 Aloysius Kippenbrock	3	S	4	W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>39413</b>	KB 3 ALOYSIUS KIPPENBROCK	3	S	4	W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>39414</b>	2B ALFRED WEYER & SON INC.	3	S	4	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							

Permit	<b>39416</b>	I-8 Alfred Weyer	3	S	4	W	Section 22
--------	--------------	------------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>41184</b>	1 Urban Hopf	2	S	6	W	Section 26
--------	--------------	--------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>15099</b>	1 FITHIAN-LYNCH	1 S	10 W	Donation
--------	--------------	-----------------	-----	------	----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>15974</b>	1 C. CHANDLER	1 S	9 W	Section 21
--------	--------------	---------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Clean oil and debris from pit areas in accordance with 312 IAC 16-5-11.

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Permit	<b>18194</b>	1 CLETUS HARDIMAN	2 S	11 W	Section 9
--------	--------------	-------------------	-----	------	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Reduce the injection pressure and / or rate to meet the specifications of the permit in accordance with 312 IAC 16-5-14.

Permit	<b>19428</b>	2 R.A. MCELLHINEY	1 S	9 W	Section 31
--------	--------------	-------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>21222</b>	1 J.H. PAYNE	2 S	13 W	Section 24
--------	--------------	--------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>21722</b>	1 K & C CROMER	3 S	9 W	Section 15
--------	--------------	----------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>22159</b>	2 C. CHANDLER	1 S	9 W	Section 21
--------	--------------	---------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>23265</b>	1 CROMER-OTTO	3 S	9 W	Section 15
--------	--------------	---------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>23673</b>	1A K & C CROMER	3 S	9 W	Section 15
--------	--------------	-----------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>23903</b>	1 CROMER-OTTO-NULL	3 S	9 W	Section 15
--------	--------------	--------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>28602</b>	2 Ed Eads	1	S	9	W	Section 17
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>33940</b>	3 J. HESTON ETAL	3	S	13	W	Section 8
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>33942</b>	1 JOSEPH HESTON ETAL	3	S	13	W	Section 8
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>37576</b>	2 R. LEFLER	3	S	9	W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:							

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Permit	<b>38327</b>	1 JERRY RILEY	3	S	9	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Permit	<b>39786</b>	CU 1 RIGGS-MARVEL	1	S	11	W	Section 18
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>40557</b>	4 RICHARD LEGLER	3	S	9	W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:							

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>41372</b>	CU 1 HOWARD & BETTY WOODS	2	S	10	W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>41516</b>	2 ELDON KRIES	3	S	13	W	Section 8
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>42688</b>	1 CHARLES PARMENTER	2	S	11	W	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>42793</b>	3 RICHARD LEFLER	3	S	9	W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>43038</b>	1 HENERY STEPHENS	1 N 10 W	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:				

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>43151</b>	3 HENERY STEPHENS	1 N 10 W	Section 20
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>43395</b>	2 CONSOL LAND DEVELOP	2 S 9 W	Section 29
The well noted above requires the following corrective action(s) to bring it into compliance:				

Permit	<b>43396</b>	3 CONSOL LAND DEVELOP	2 S 9 W	Section 29
The well noted above requires the following corrective action(s) to bring it into compliance:				

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>43399</b>	1-WI CONSOL. LAND DEVELOP. CO.	2 S 9 W	Section 29
The well noted above requires the following corrective action(s) to bring it into compliance:				

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>43400</b>	5WI CONOL LAND DEVEL	2 S 9 W	Section 29
The well noted above requires the following corrective action(s) to bring it into compliance:				

Permit	<b>44806</b>	1 HENRY MORGAN	3 S 9 W	Section 3
The well noted above requires the following corrective action(s) to bring it into compliance:				

Submit Quarterly Monitoring Report in accordance with 312 IAC 16-5-18.

Permit	<b>44858</b>	1-WI HARVEY KOLB UNIT	1 S 10 W	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:				

Permit	<b>45940</b>	78X-14 Amanta Maier	3 S 14 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>46961</b>	1 Constance Nurrenbern	2	S	10	W	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>47203</b>	1 KARL HAWLES	3	S	9	W	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:							

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Permit	<b>48862</b>	#1 HALL-HORRALL	1	S	10	W	Location
The well noted above requires the following corrective action(s) to bring it into compliance:							

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48863</b>	#1 HELEN HORRALL	1	S	10	W	Location
The well noted above requires the following corrective action(s) to bring it into compliance:							

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Perform cleanup operations to properly remove and dispose of oil which was spilled at your facility as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49994</b>	1 SUSAN KOLB MAYER	1	S	10	W	Location
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Permit	<b>43062</b>	1 THOMAS C. & HILDA MARTIN	6 N	5 W	Section 17
The well noted above requires the following corrective action(s) to bring it into compliance:					

Remove casing to a depth of three (3) feet, remove equipment and debris and restore site to as near pre-drilling conditions as possible in accordance with 312 IAC 16-5-19.

Permit	<b>28425</b>	2 W. H. FOX	6	S	5	E	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Cease well operations and repair all equipment as needed to prevent the migration of fluids within the well annuli per 312 IAC 16-5-13.

County Jay

Permit	<b>39099</b>	1 WILLIAM NUCKOLS	22 N 14 E	Section 26
The well noted above requires the following corrective action(s) to bring it into compliance:				

Plug and abandon the well in accordance with 312 IAC 16-5-19. NOTE: This well is not permitted and may not be operated or temporarily abandoned.

Permit	<b>9089</b>	2 MONTGOMERY HRS	5	N	7	W	Section 28
--------	-------------	------------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Permit	<b>9827</b>	2 GEORGE STECKLER	1	N	12	W	Section 36
--------	-------------	-------------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>10815</b>	1 FRANCIS PARKINSON	1	N	12	W	Section 36
--------	--------------	---------------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>10887</b>	1 G. STECKLER	1	N	12	W	Section 36
--------	--------------	---------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>10950</b>	1 G. STECKLER	1	N	12	W	Section 36
--------	--------------	---------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>11684</b>	2 G. STECKLER	1	N	12	W	Section 36
--------	--------------	---------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>11937</b>	A-2 G. STECKLER	1	N	12	W	Section 36
--------	--------------	-----------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>11986</b>	A-3 G. STECKLER	1	N	12	W	Section 36
--------	--------------	-----------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>23466</b>	5-A G. & E. STECKLER	1	N	12	W	Section 36
--------	--------------	----------------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>23472</b>	3 G. & E. STECKLER	1	N	12	W	Section 36
--------	--------------	--------------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>35577</b>	2 N. WALDEN	5 N 10 W	Section
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>36405</b>	1 KEN KOENIG	5 N 7 W	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:				

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Permit	<b>36722</b>	1 WOOD HRS	5 N 7 W	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:				

Permit	<b>36723</b>	3 WOOD HEIRS	5 N 7 W	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:				

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Permit	<b>36837</b>	1 Field Farms	1 N 10 W	Survey 1
The well noted above requires the following corrective action(s) to bring it into compliance:				

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Permit	<b>48630</b>	1 BERTIE TAYLOR	1 N 8 W	Location 7
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>48648</b>	1 PAUL LIKE	2 N 9 W	Donation
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>48834</b>	#2 SWD SUSAN STANBRO	1 N 10 W	Section 8
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Permit	<b>48968</b>	522 CLAYPOLE HILLS UNIT	1 N 12 W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>48969</b>	4-A Claypole Hills Unit	1 N 12 W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:				

Permit	<b>48982</b>	A-1 CLAYPOLE HILLS UNIT	1 N 12 W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:				

Permit	<b>49695</b>	526 JOE STECKLER	1	N	12	W	Section 25
--------	--------------	------------------	---	---	----	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>17224</b>	2 FRANK DANIELS	27 N	5 E	Section 19
--------	--------------	-----------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>41235</b>	1 WOODRUFF	27 N	5 E	Section 19
--------	--------------	------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>41748</b>	2 HERBERT & BETTY EBERT	27 N	4 E	Section 22
--------	--------------	-------------------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Permit	<b>41911</b>	1 NELLIE LAWRENCE	27 N	4 E	Section 22
--------	--------------	-------------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>41958</b>	1 WEISELL BABER	27 N	4 E	Section 21
--------	--------------	-----------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>42273</b>	1-82 OPAL ARNHOLT	27 N	5 E	Section 19
--------	--------------	-------------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48701</b>	1 BECK	27 N	5 E	Section 18
--------	--------------	--------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>48760</b>	5 GRETZINGER	27 N	4 E	Section 29
--------	--------------	--------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48893</b>	9 GRETZINGER	27 N	4 E	Section 29
--------	--------------	--------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48925</b>	12A WILLIS & JOYCE MARBURGER	27 N	4 E	Section 29
--------	--------------	------------------------------	------	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Permit	<b>48929</b>	7A WILLIS & JOYCE MARBURGER	27	N	4	E	Section 29
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>48940</b>	2 KOKOMO TUBE INC.	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Repair the pipes conveying waste fluids and repair all damage caused by the escape of fluids per 312 IAC 16-5-13.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Perform cleanup operations to properly remove and dispose of oil which was spilled at your facility as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48941</b>	#1 KOKOMO TUBE INC.	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49050</b>	7 BABER	27	N	4	E	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:							

Perform cleanup operations to properly remove and dispose of oil which was spilled at your facility as per 312 IAC 16-5-11.

Permit	<b>49080</b>	18 SOAMES	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49096</b>	19 SOAMES	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>49147</b>	3 KOKOMO TUBE	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49201</b>	2 ROCK INDUSTRIES	27	N	4	E	Section 29
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49212</b>	#5B TILLETT	27	N	4	E	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49216</b>	2 WEISELL BABER	27	N	4	E	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49218</b>	3 SNOWDEN BABER	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49223</b>	6C SOAMES	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49228</b>	205 SOAMES	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49229</b>	#210 SOAMES	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49231</b>	6B TILLET	27	N	4	E	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49303</b>	8 BABER	27	N	4	E	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49587</b>	#4 COLE	27	N	4	E	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49636</b>	2 ALBERT COLE	27	N	4	E	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:							

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Permit	<b>49696</b>	19-S20 SOAMES	27	N	4	E	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>41989</b>	3 JOSEPH & AGNES LASHER	5 S	3 W	Section 2
--------	--------------	-------------------------	-----	-----	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>41990</b>	4 JOSEPH & AGNES LASHER	5 S	3 W	Section 2
--------	--------------	-------------------------	-----	-----	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>45253</b>	1 EUGENE LYONS	3 S	3 W	Section 26
--------	--------------	----------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48774</b>	#1 CHARLES WERNER	6 S	3 W	Section 8
--------	--------------	-------------------	-----	-----	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>48900</b>	1 LOUIS & AGNES EVRARD	5 S	2 W	Section 17
--------	--------------	------------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>3910</b>	4 ALICE STEWART	1	N	9	W	Survey 16
--------	-------------	-----------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>5104</b>	2 WM & NANCY COFFMAN	1	N	9	W	Section 22
--------	-------------	----------------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>5153</b>	2 ESSIE STEWART	1	N	9	W	Survey 15
--------	-------------	-----------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>5311</b>	3 ESSIE STEWART	1	N	9	W	Section 22
--------	-------------	-----------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>5312</b>	3 WM. COFFMAN	1	N	9	W	Section 22
--------	-------------	---------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>6508</b>	2 HARRY HUNTER	1	N	9	W	Section 15
--------	-------------	----------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>6654</b>	5 GERALD WIREY	1	S	9	W	Section 9
--------	-------------	----------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>7497</b>	1 DENVER MCROBERTS	1	S	9	W	Section 10
--------	-------------	--------------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>7986</b>	1A GERALD WIREY	1	S	9	W	Section 4
--------	-------------	-----------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>8141</b>	2A GERALD WIREY	1	S	9	W	Section 4
--------	-------------	-----------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>9366</b>	4A GERLAND WIREY	1	S	9	W	Section 4
--------	-------------	------------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>11418</b>	6A GERALD WIREY	1	S	9	W	Section 4
--------	--------------	-----------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>11993</b>	6 GERALD WIREY	1	S	9	W	Section 9
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>12420</b>	1 MOSES HOWARD, ET AL COMM.	1	S	8	W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>12473</b>	2 MOSES HOWARD, ET ALL COMM	1	S	8	W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>12551</b>	1 C. & E. STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>13209</b>	10 JESSE BARRETT	1	S	9	W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>13747</b>	5 JESSE BARRETT	1	S	9	W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>13748</b>	1 JESSE BARRETT	1	S	9	W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>13788</b>	1 IRA COPELAND	2	S	8	W	Section 27
The well noted above requires the following corrective action(s) to bring it into compliance:							

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Permit	<b>13875</b>	6 ALICE STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>14042</b>	E-3 ALICE STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>14043</b>	E-4 ALICE STEWART	1	N	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>14044</b>	F-4 ALICE STEWART	1	N	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							
Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.							
Permit	<b>14168</b>	3A ESSIE STEWART	1	N	9	W	Survey 15
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>14300</b>	7 ALICE STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>14301</b>	8 ALICE STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>14302</b>	G-4 ALICE STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>15087</b>	4 CLARENCE & ESSIE STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>15088</b>	3 CLARENCE & ESSIE STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>15146</b>	G-3 ALICE STEWART	1	N	9	W	Survey 16
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>15211</b>	8 ESSIE STEWART	1	N	9	W	Survey 15
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>15220</b>	H-3 ESSIE STEWART	1	N	9	W	Location 25
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>15221</b>	E-2 ESSIE STEWART	1	N	9	W	Survey 15
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>15222</b>	F-2 ESSIE STEWART	1	N	9	W	Survey 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>15260</b>	D-2 ESSIE STEWART	1	N	9	W	Survey 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>15442</b>	9 ESSIE STEWART	1	N	9	W	Survey 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>16336</b>	W-1 WM. H. COFFMAN	1	N	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>16337</b>	W-2 WM. H. COFFMAN	1	N	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>16338</b>	W-2 ESSIE STEWART	1	N	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>17182</b>	1 WM. COFFMAN	1	N	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>17943</b>	3 DENVER MCROBERTS	1	S	9	W	Section 10
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>18958</b>	1 SIMON KENDALL	1	N	9	W	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>19033</b>	4B GERALD WIREY	1	S	9	W	Section 4
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>19260</b>	IR-1 SAMUEL E. NEWELL	1	N	9	W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>19261</b>	IR-1 SAMUEL E. NEWELL	1	N	9	W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>19644</b>	1 M. HUBBARD UNIT	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>19667</b>	2 ALICE STEWART	1	N	9	W	Survey 17
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>19755</b>	1C E. MILLER HRS ETAL	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>19807</b>	2B GERALD WIREY	1	S	9	W	Section 4
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>19817</b>	5 ALICE STEWART	1	N	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>19937</b>	1 NEWELL-GLADISH	1	N	9	W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>19965</b>	1A NEWELL-GLADISH	1	N	9	W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>19972</b>	1 GLADISH-WILLIS	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>20290</b>	2 MILBURN HUBBARD	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>20336</b>	2 GLADISH-WILLIS UNIT	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>20386</b>	1A W.V.MCCULLOUGH	1	N	9	W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>20480</b>	1 W.V. MCCULLOUGH	1	N	9	W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>20793</b>	2 WILLIS COMM	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>21416</b>	1A ESTER HUNTER	1	N	9	W	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>21723</b>	1 W. WERNER ETAL	2	S	8	W	Section 35
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>22616</b>	1A W.COFFMAN	1	N	9	W	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>23628</b>	3 IRA COPELAND	2	S	8	W	Section 27
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>24772</b>	1 WM CORN	2	S	8	W	Section 27
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>26203</b>	1 WYATT-RAUCH FARMS	1	S	8	W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>26786</b>	1 M. MILLER	1	S	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>26829</b>	2 M. MILLER	1	S	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>26838</b>	3 M. MILLER	1	S	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>26870</b>	3A M. MILLER	1	S	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>27022</b>	6-W MASTERS-COATES ETAL	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>27474</b>	2A WM.COFFMAN	1	N	9	W	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>27516</b>	8-W LOVELESS,MASTER,BARRETT	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>27819</b>	1 MILLER ETAL	1	S	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>28045</b>	1 ELLA MILLER HRS	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>28890</b>	CU 1 HERMAN ATKINSON	1	S	9	W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>29235</b>	1 CECIL HAMM ETAL	1	S	7	W	Section 30
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>29777</b>	3 WYATT-RAUCH FARMS, INC.	1	S	8	W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>30251</b>	3 C & M HAMM	1	S	7	W	Section 30
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>31179</b>	1 CARLOS & POLLY CRECELUIS	1	S	9	W	Section 12
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate, or plug and abandon the well or obtain a temporary abandonment permit for the well per IC 14-37-8.

Permit	<b>31238</b>	1 AETNA LIFE INS-CRECELIUS	1	S	9	W	Section 12
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>32613</b>	3 RUFUS BECK	1	S	8	W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>32811</b>	W-2 ERNEST WILSON	1	S	9	W	Section 13
The well noted above requires the following corrective action(s) to bring it into compliance:							

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>33005</b>	1 BOBBY WILLIS	1	S	9	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>33578</b>	3 W. & L. BURNETT	2	S	8	W	Section 27
The well noted above requires the following corrective action(s) to bring it into compliance:							

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>34317</b>	1 MALCOLM & BERTHA NIXON	2	S	8	W	Section 13
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>39208</b>	2 HELEN & WILLIAM CALLAWAY	2	S	7	W	Section 29
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>39567</b>	1 INSTATE COMM. & V. WOOLSE	2	S	7	W	Section 29
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>39941</b>	1 LINUS STENFTENAGEL	3	S	6	W	Section 19
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>40467</b>	11 HOWARD CLEFF	1	S	9	W	Section 9
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>41202</b>	1 F.W. WESTERN	1	S	9	W	Section 4
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>41282</b>	3 FORREST WESTERN	1	S	9	W	Section 4
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>41873</b>	5 R & M STRICKLAND	2 S 8 W	Section 27
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>41874</b>	6 R & M STRICKLAND	2 S 8 W	Section 27
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>42314</b>	#1 WARNER LOVELESS	1 S 8 W	Section 31
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>42401</b>	1 WILDER-PHILLIPS-BROSHEARS	1 S 7 W	Section 35
The well noted above requires the following corrective action(s) to bring it into compliance:				

Permit	<b>42683</b>	1A R & M STRICKLAND	2 S 8 W	Section 27
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>43126</b>	14 HOWARD CLEFF	1 S 9 W	Section 4
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>43141</b>	15 HOWARD CLEFF	1 S 9 W	Section 4
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>43170</b>	15 HOWARD CLEFF	1 S 9 W	Section 4
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>43388</b>	2 F.E. WESTERN	1 N 9 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Cease all operations at this well, obtain and post the required permit, or plug and abandon the well in accordance with 312 IAC 16-5-19. (NOTE: The penalty must be paid before a permit can be issued.)

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Permit	<b>45489</b>	4 LOBREE & WYASTT-RAUSCH	1 S 8 W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:				

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Submit Quarterly Monitoring Report in accordance with 312 IAC 16-5-18.

Permit	<b>45981</b>	1 HOWARD WYLIE COMM.	1 S 7 W	Section 35
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>46772</b>	2 MALCOLM & BERTHA NIXON	2 S	8 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>47490</b>	1 HOUCHINS COMM.	1 S	8 W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:					

Permit	<b>47492</b>	4 E WELTON	1 S	8 W	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>47497</b>	2 HOUCHINS COMM.	1 S	8 W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>47869</b>	1 CLARENCE C. COOK	2 S	7 W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:					

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48039</b>	1 ZACK WELTON HEIRS	1 S	8 W	Section 20
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48042</b>	5 IDA DORSAM	1 S	8 W	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>48043</b>	3 EMMA WELTON	1 S	8 W	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>48066</b>	1 EMA WELTON	1 S	8 W	Section 21
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>48280</b>	1 RANDALL SMITH	2 S	7 W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:					

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Properly remove and dispose of oil and waste fluids from the inside of the firewall per 312 IAC 16-5-11.

Permit	<b>49378</b>	A-1 SKINNER HEIRS	2 S	8 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>50843</b>	#1 SAM RUMBLE	1	S	9	W	Section 2
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>50854</b>	1 ERNET WILSON	1	S	9	W	Section 13
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>50874</b>	3 M. INGLER	1	S	9	W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:							
Permit	<b>51433</b>	4 JAMES RUMBLE	1	N	9	W	Section 36
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>1167</b>	1 F.O. FAUL HEIRS	4 S	14 W	Section 11
--------	-------------	-------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>1414</b>	1 HENRY A & IDA WEDEKING	6 S	13 W	Section 23
--------	-------------	--------------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>3416</b>	9 ELMER ELLIOTT	5 S	14 W	Section 14
--------	-------------	-----------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>3480</b>	2 ELMER E. ELLIOTT	5 S	14 W	Section 23
--------	-------------	--------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>3570</b>	5 ELMER E. ELLIOTT	5 S	14 W	Section 23
--------	-------------	--------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>3580</b>	1A E.E. ELLIOTT	5 S	14 W	Section 23
--------	-------------	-----------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>3607</b>	12 ELMER ELLIOTT	5 S	14 W	Section 14
--------	-------------	------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>3649</b>	5 ELMER E. ELLIOT	5 S	14 W	Section 23
--------	-------------	-------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>3723</b>	14 ELMER E. ELLIOTT	5 S	14 W	Section 14
--------	-------------	---------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>3826</b>	4A ELMER E. ELLIOTT	5 S	14 W	Section 23
--------	-------------	---------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>3827</b>	5-A ELMER E. ELLIOT	5 S	14 W	Section 23
--------	-------------	---------------------	-----	------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Perform cleanup operations to properly remove and dispose of oil which was spilled at your facility as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>3837</b>	1-A ELMER E. ELLIOT	5 S	14 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>4003</b>	11 E E ELLIOTT	5 S	14 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>5029</b>	8A WLMER E. ELLIOTT	5 S	14 W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>5061</b>	9A ELMER E. ELLIOTT	5 S	14 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>5165</b>	1 COMM. WILLIAM OETH	7 S	12 W	Section 5
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>5500</b>	19 ELMER ELLIOTT	5 S	14 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>11408</b>	2 C.P SLYGH	6 S	13 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>12942</b>	1 A. ALLYN	7 S	12 W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:					

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>13545</b>	1 J. MUELLER	7 S	12 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>13825</b>	1 A.L. JOHNSON	4 S	13 W	Section 33
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>15180</b>	2 FRED ROEHR	6 S 12 W	Section 18
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>15538</b>	1 IRA ROTHROCK	6 S 12 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>16201</b>	2 IRA ROTHROCK	6 S 12 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>17757</b>	9 JOEL VAIL	5 S 14 W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Submit Quarterly Monitoring Report in accordance with 312 IAC 16-5-18.

Permit	<b>18605</b>	3 IRA ROTHROCK	6 S 12 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>19380</b>	1 MARY OETH	6 S 12 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>23018</b>	1 M. OETH	7 S 12 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>25128</b>	6 E.E. ELLIOTT	5 S 14 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>25911</b>	1 CLARA NASH	7 S 14 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>26001</b>	3 IFB-ELLIOTT	5 S 14 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>26014</b>	3-W BREHM-ELLIOTT	5 S 14 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>28760</b>	1 C. A. Walters	7 S 14 W	Section 12
The well noted above requires the following corrective action(s) to bring it into compliance:				

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>31059</b>	1 CHARLES. P. SLYGH	6 S 13 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>31060</b>	2 W.F. SCHREIBER	6 S 13 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>31061</b>	1 W.F. SCHREIBER	6 S 13 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>31839</b>	2 Harmon	4 S 13 W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:				

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>32087</b>	1 RALPH NOTTER	6 S 13 W	Section 10
The well noted above requires the following corrective action(s) to bring it into compliance:				

Per IC 14-37, pay the annual fee of \$50.00 and a penalty of \$500.00.

Permit	<b>32215</b>	24 L.P. Kleiderer A Unit	3 S 14 W	Section 33
The well noted above requires the following corrective action(s) to bring it into compliance:				

Cease injection, case, cement casing or otherwise reconstruct the well to conform to the provisions of 312 IAC 16-5-9.

Permit	<b>32220</b>	1-W T.H. KAFFENBERGER	6 S 13 W	Section 10
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>32744</b>	1 MARC STEVENS	6 S 13 W	Section 10
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>32965</b>	1-W MORTON ELLIOTT	5 S 14 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:				

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>33663</b>	4-W ASHLAND VAIL	5 S 14 W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Submit Quarterly Monitoring Report in accordance with 312 IAC 16-5-18.

Permit	<b>34968</b>	1 JACKSON-ESCHE-BREEZE	6 S 13 W	Section 11
The well noted above requires the following corrective action(s) to bring it into compliance:				

Per IC 14-37, pay the annual fee of \$50.00 and a penalty of \$500.00.

Permit	<b>40291</b>	6 CLARA NASH	7 S 14 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>40292</b>	7 CLARA NASH	7 S 14 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>40983</b>	13 E.E. ELLIOTT	5 S 14 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:				

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>41559</b>	1 DORA NASH	7 S 14 W	Section 32
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>42391</b>	1 WALTER WASSON	5 S 13 W	Section 34
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>42572</b>	2 WI Ralph Thornburg	5 S 13 W	Section 12
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>42611</b>	3 RALPH E. THORNBURG ETAL	5 S 13 W	Section 12
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>46833</b>	1-A Dausman Estate	7 S 12 W	Section 5
The well noted above requires the following corrective action(s) to bring it into compliance:				

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>47190</b>	7 CLAUDE RICKETTS	6 S 13 W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48773</b>	7 M. Dixon	8 S 13 W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48775</b>	#3 Mary Dixon	8 S 13 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48776</b>	#1 R. Hardwick	8 S 13 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48777</b>	#1 B. Eilert	8 S 13 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48778</b>	W-1 B. Eilert & A. C. Ries	8 S 13 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48779</b>	1 E. Erwin	8 S 13 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48780</b>	#1-A E. Erwin	8 S 13 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48781</b>	2-A E. & W.H. Erwin	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>48782</b>	3 E. Erwin	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.							
Permit	<b>48783</b>	#1-A Dixon Heirs	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>48784</b>	#2A Mary Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>48785</b>	3A E. & W. H. Erwin	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.							
Permit	<b>48786</b>	10 M. Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.							
Permit	<b>48788</b>	3 W.O. Klotz	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.							
Permit	<b>48789</b>	5 Erwin Heirs	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.							
Permit	<b>48790</b>	2 Erwin Heirs	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.							
Permit	<b>48792</b>	6 Mary Dixon	8	S	13	W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.							
Permit	<b>48793</b>	5 SOUTH POWELL'S LAKE FIELD	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							
Permit	<b>48794</b>	#11 M. Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							
Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.							

Permit	<b>48795</b>	#1 Mary Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease drainage of fluids into or from unauthorized pits or firewall, remove drainage pipes and repair all damage caused by the escape of fluids per 312 IAC 16-5-13.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48796</b>	5 Mary Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48797</b>	9 M. Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48798</b>	#1 W. Klotz	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48799</b>	#8 M. Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48800</b>	2 M. Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48801</b>	1 Hastings-Highman	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48802</b>	13 Mary Dixon	8	S	13	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>48816</b>	1-B STATE OF IND-HARMONY PARK	5	S	14	W	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							

Perform cleanup operations to properly remove and dispose of oil which was spilled at your facility as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Permit	<b>44110</b>	1 COMM. R.&R. SINGLETON & GOOD	29	N	3	W	Section 35
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>30922</b>	1 FRED TIBBETTS	20 N 15 E	Section 19
--------	--------------	-----------------	-----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Repair all well equipment and facilities to prevent the escape of oil or gas as per 312 IAC 16-5-13.

Permit	<b>31758</b>	1 JAMES A. FRAZIER	20 N 15 E	Section 32
--------	--------------	--------------------	-----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>35789</b>	1 HAROLD EVERHART	13	N	7	E	Section 4
The well noted above requires the following corrective action(s) to bring it into compliance:							

Re-case the well and obtain a temporary abandonment permit, or plug and abandon the well as per IC 14-37-8. NOTE: This well does not qualify for a temporary abandonment permit in its present condition.

Permit	<b>1120</b>	1 BEN H. SHROUDS	8 S	6 W	Section 5
--------	-------------	------------------	-----	-----	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>3279</b>	1 MONTGOMERY-EBLEY	7 S	7 W	Section 30
--------	-------------	--------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>3707</b>	6 ANSELM EBLE	7 S	7 W	Section 7
--------	-------------	---------------	-----	-----	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>15469</b>	5 VANCE GRIPPENSTROH	5 S	5 W	Section 22
--------	--------------	----------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>16360</b>	1 J.SAM VARNER	6 S	5 W	Section 24
--------	--------------	----------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>16700</b>	3 J. SAM & ALBERT VARNER	6 S	5 W	Section 24
--------	--------------	--------------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Repair the pipes conveying oil and repair all damage caused by the leakage of oil in accordance with 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>16876</b>	2 J. DAUBY	6 S	5 W	Section 24
--------	--------------	------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Set surface casing below all potable aquifers or circulate cement on the production string of casing in accordance with 312 IAC 16-5-9.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>17481</b>	1-B EDWARD HAGAN	6 S	5 W	Section 24
--------	--------------	------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>17600</b>	3 HERMAN & COVA HOWELL	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>17913</b>	4 HERMAN & CORA HOWELL	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Permit	<b>18000</b>	4B EDWARD E. HAGAN	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>18344</b>	1 EDWARD E. HAGAN	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>19323</b>	2 C.C. COTTON	6	S	5	W	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>19763</b>	1 JOHN RAAF	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>19764</b>	4 J. & A. VARNER	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Permit	<b>19970</b>	1 D. SPRINKLE	6	S	4	W	Section 11
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>20309</b>	W-2 D. SPRINKLE	6	S	4	W	Section 11
The well noted above requires the following corrective action(s) to bring it into compliance:							

Submit Quarterly Monitoring Report in accordance with 312 IAC 16-5-18.

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>20310</b>	W-1 D. SPRINKLE	6	S	4	W	Section 11
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>20523</b>	1 M. JACOB HEIRS	6	S	4	W	Section 11
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>20864</b>	4 D. SPRINKLE	6	S	4	W	Section 11
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>21285</b>	4 J. DAUBY	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>21543</b>	2 E. HAGAN	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>21544</b>	1 H.HOWELL	6	S	5	W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>22392</b>	2 J & M PROPERTIES, INC.	6	S	4	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>22499</b>	3 F.W. GRASS	6	S	4	W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>22584</b>	3 J & M PROPERTIES, INC.	6	S	4	W	Section 11
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>23138</b>	4 J & M PROPERTIES, INC.	6	S	4	W	Section 12
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Cease injection into and plug the well per 312 IAC 2116-5-19.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>23757</b>	1 J.D. SIMS	7 S	7 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:					

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>24105</b>	1 MARY EGER	6 S	4 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>24635</b>	1 W.H & B.G. SCHNAKE	6 S	4 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>24681</b>	6 J & M PROPERTIES, INC.	6 S	4 W	Section 13
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>25651</b>	5 DAVID SPRINKLE	6 S	4 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>26735</b>	3 H. WISEMAN	6 S	4 W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Submit Quarterly Monitoring Report in accordance with 312 IAC 16-5-18.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>26740</b>	1 ELMER PRUESS	6 S	4 W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Submit Quarterly Monitoring Report in accordance with 312 IAC 16-5-18.

Permit	<b>26820</b>	1 JOHN RAAF	6 S	5 W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:					

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Permit	<b>26821</b>	2-B EDWARD HAGAN	6 S	5 W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:					

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>26822</b>	4 JOHN RAAF	6 S	5 W	Section 24
The well noted above requires the following corrective action(s) to bring it into compliance:					

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>31091</b>	2 LOUIS MEYER	4 S	5 W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>31325</b>	1 MARY BARRON	7 S	7 W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:					

Perform cleanup operations to properly remove and dispose of oil which was spilled at your facility as per 312 IAC 16-5-11.

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Permit	<b>32983</b>	1 MILLER-POUNDS	7 S	7 W	Section 31
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>33116</b>	1 Hedges	7 S	7 W	Section 30
The well noted above requires the following corrective action(s) to bring it into compliance:					

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>33205</b>	1 C & G HEDGES	7 S	7 W	Section 31
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Plug and abandon the well in accordance with 312 IAC 16-5-19. NOTE: This well is not permitted and may not be operated or temporarily abandoned.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>33557</b>	3 LOUIS MEYER	4 S	5 W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:					

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Install connections as required to allow field inspector to monitor tubing and annulus pressures at the wellhead per 312 IAC 16-5-14.

Permit	<b>33657</b>	1 LOUIS MEYER	4 S	5 W	Section 22
The well noted above requires the following corrective action(s) to bring it into compliance:					

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>35762</b>	1-A A.J. SAUTER	6	S	5	W	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection and repair or replace all equipment so as to confine injected fluids to the permitted interval per 312 IAC 16-5-15.  
NOTE: A successful demonstration of mechanical integrity is required after repair.

Permit	<b>36400</b>	2-I J.D. HOPKINS	6	S	4	W	Section 15
The well noted above requires the following corrective action(s) to bring it into compliance:							

Replace the bond or plug and abandon the well in accordance with 312 IAC 16-5-19.

Permit	<b>38309</b>	1 MATTINGLY & PATMORE	7	S	7	W	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>40527</b>	4 WM MACHIN	7	S	5	W	Section 6
The well noted above requires the following corrective action(s) to bring it into compliance:							

Cease injection and repair or replace all equipment so as to confine injected fluids to the permitted interval per 312 IAC 16-5-15.  
NOTE: A successful demonstration of mechanical integrity is required after repair.

Permit	<b>41138</b>	2-A LOLA MAE ABBOTT	7	S	7	W	Section 7
The well noted above requires the following corrective action(s) to bring it into compliance:							

Reduce the injection pressure and / or rate to meet the specifications of the permit in accordance with 312 IAC 16-5-14.

Permit	<b>43376</b>	1 JAMES CLARK	6	S	4	W	Section 3
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>47305</b>	1-A RUTH SOUDER	6	S	4	W	Section 2
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>47723</b>	A-7 WINKLER	6	S	5	W	Section 28
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Permit	<b>48416</b>	1 R. & L. CRON	7	S	7	W	Section 5
The well noted above requires the following corrective action(s) to bring it into compliance:							

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>23093</b>	L-9 JOSEPHINE DIX	8 N 10 W	Section 1
--------	--------------	-------------------	----------	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>32604</b>	1 T. ABRAMS	5 N 10 W	Section 3
--------	--------------	-------------	----------	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>33180</b>	4-A S.E. LINDLEY	8 N 11 W	Section 13
--------	--------------	------------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48987</b>	1 PAUL LARR	9 N 8	Section 9
--------	--------------	-------------	-------	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>49553</b>	1 HIATT	7 N 9 W	Section 23
--------	--------------	---------	---------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>7458</b>	1 Gartner Community	7 S 11 W	Section 15
--------	-------------	---------------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>7597</b>	1 JOHN STEINKAMP	7 S 11 W	Section 16
--------	-------------	------------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>12771</b>	I-2 KAMP-HAPPE	7 S 11 W	Section 15
--------	--------------	----------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Cease injection and provide requested information per 312 IAC 16-5-16.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>17631</b>	2 WALLER ETAL	7 S 11 W	Section 18
--------	--------------	---------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Permit	<b>17702</b>	2 P. & I. BURGDORF	7 S 11 W	Section 18
--------	--------------	--------------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>18362</b>	1 WALTER JOECKEL	7 S 11 W	Section 18
--------	--------------	------------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Permit	<b>20413</b>	1 KAMP	7 S 11 W	Section 15
--------	--------------	--------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>24555</b>	2 LAUBSCHER COMMUNITY	5 S 10 W	Section 31
--------	--------------	-----------------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>24556</b>	1 STUCKI ETAL	5 S 11 W	Section 36
--------	--------------	---------------	----------	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Permit	<b>24967</b>	I-10 JOHN STEINKAMP	7 S 11 W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Permit	<b>25618</b>	I-12 JOHN STEINKAMP	7 S 11 W	Section 16
The well noted above requires the following corrective action(s) to bring it into compliance:				

Cease injection, perform and pass a mechanical integrity test as prescribed by 312 IAC 16-5-15.

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Permit	<b>29018</b>	1B LUISE & PAUL BURGDORF	7 S 11 W	Section 18
The well noted above requires the following corrective action(s) to bring it into compliance:				

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Clean oil and debris from pit areas in accordance with 312 IAC 16-5-11.

Permit	<b>35456</b>	3 ANNA & WALTER JOECKEL	7 S 11 W	Section 18
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>35619</b>	3B LOUISE BECKER BURGDORF	7 S 11 W	Section 18
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>36387</b>	1 COMM E.H. BROMM, ETAL	5 S 11 W	Section 14
The well noted above requires the following corrective action(s) to bring it into compliance:				

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Permit	<b>39187</b>	6 L. B. Burgdorf	7 S 11 W	Section 18
The well noted above requires the following corrective action(s) to bring it into compliance:				

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>30481</b>	2H JOHN CHAMERLAIN	28	N	6	E	Section 13
--------	--------------	--------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>30487</b>	4 JOHN CHAMBERLAIN	28	N	6	E	Section 13
--------	--------------	--------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Properly fill and level the pit per 312 IAC 16-5-13. NOTE: Evaporation pits are prohibited.

Permit	<b>30518</b>	2 JOHN CHAMBERLAIN	28	N	6	E	Section 13
--------	--------------	--------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>30519</b>	3 JOHN CHAMBERLAIN	28	N	6	E	Section 13
--------	--------------	--------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , formally T / A, plug and abandon, or re-permit for production in accordance with IC 14-37-8. NOTE: Operation and T / A require a pressure test.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>30551</b>	4H JOHN CHAMBERLAIN	28	N	6	E	Section 13
--------	--------------	---------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>30658</b>	5-H JOHN W. CHAMBERLAIN	28	N	6	E	Section 13
--------	--------------	-------------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>33448</b>	6SC JOHN W. CHAMBERLAIN	28	N	6	E	Section 13
--------	--------------	-------------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>39283</b>	1 JOHN & OMBRA KEEFABER	28	N	6	E	Section 23
--------	--------------	-------------------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10. NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>40427</b>	3 KEEFABER	28	N	6	E	Section 23
--------	--------------	------------	----	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>42266</b>	5 KEFFABER	28	N	6	E	Section 23
The well noted above requires the following corrective action(s) to bring it into compliance:							

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.  
NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>29680</b>	3 J.R. SCALES	5 S	6 W	Section 5
--------	--------------	---------------	-----	-----	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Construct a firewall that Forms a continuous barrier around the tank battery capable of holding one and one-half (1 1/2) times the battery capacity in accordance with 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>32199</b>	1 JOHN RAYMOND SCALES	5 S	6 W	Section 8
--------	--------------	-----------------------	-----	-----	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>40406</b>	1 WILLARD MEYER FARMS INC.	4 S	6 W	Section 10
--------	--------------	----------------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>40872</b>	1 ELOISE MOESNER	4 S	6 W	Section 11
--------	--------------	------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>41553</b>	1 WIEBE COMMUNITY	4 S	6 W	Section 10
--------	--------------	-------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>42063</b>	1 MOESNER MEYER KUHN	4 S	6 W	Section 11
--------	--------------	----------------------	-----	-----	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Remove all vegetation and inflammable materials from all well operations and facilities as per 312 IAC 16-5-11.

Permit	<b>42529</b>	1 L.&D. HILDENBRAND/ST. IN.	4 S	6 W	Section 1
--------	--------------	-----------------------------	-----	-----	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>45742</b>	1 John King etal	5	S	7	W	Section 5
--------	--------------	------------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Perform cleanup operations to properly remove and dispose of oil which was spilled at your facility as per 312 IAC 16-5-11.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

Permit	<b>46825</b>	1 CHARLES W. SCHAAD	5	S	7	W	Section 28
--------	--------------	---------------------	---	---	---	---	------------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Permit	<b>48447</b>	1 GLENNETH KOHLMAYER	4	S	9	W	Section 8
--------	--------------	----------------------	---	---	---	---	-----------

The well noted above requires the following corrective action(s) to bring it into compliance:

Operate , or plug and abandon , or obtain a temporary abandonment permit for the well per 312 IAC 16-5-20. NOTE: A pressure test is required prior to obtaining a temporary abandonment permit.

Post well and lease identification showing the Permit Number, Lease Name, Section, Township and Range per 312 IAC 16-5-10.

NOTE: This identification must be readable from 20 feet.

